



Village of
Rantoul

333 S. Tanner
Rantoul, Ill 61866

Phone 217.896.6896
Email: evences@myrantoul.com

March 09, 2018

505 CONDIT DRIVE ROOF REPLACEMENT & 6 AVIATION CENTER ROOF REPAIR
Village of Rantoul
#VRNTL-18-B-03

ADDENDUM #1

Add the following information to the "ROOF REPAIR PROJECT" bid documents

Item 1. Revised Scope of Work

505 CONDIT ROOF REPLACEMENT

Item No.	Description	Quantity	Unit Price	Amount
1	Remove/Dispose & Replace 3 Tab 25yr Composite Shingle roofing	274 Squares		
2	Lower Right corner replace sheathing-plywood 1/2" *See Sketch*	32SF		
3	Replace Drip Edge	840 LF		
4	Roofing Felt	274 Squares		
5	Install Ridge Vent	270 LF		
6	Install new flashing at pipe jacks	16		
			TOTAL:	


NOTE: See Roof F2(B) of attached sketch page 1

6 AVIATION CENTER ROOF REPAIR

Item No.	Description	Quantity	Unit Price	Amount
1	Remove/Dispose & Replace 7 standing seem metal panels.	560SF		
2	Detach and reset 7 panels above the damaged panels.	560SF		
3	Install Paper faced Insulation	560SF		
4			TOTAL:	

NOTE: See Roof sketch page 2

SKETCH2 - Main Level



Main Level